



1200 3 POINT FORK ASSEMBLY




ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	RA-1200	1200 3 Point Fork Weldment	1
2	P728	Cat 1 Draw Pin	2
3	CP-0164-4	Top link Bushing	1
4	064-014-1	Nylock Nut, 3/4"-10 NC	1
5	007-211-1	Hex Head Cap Screw, 3/4-10 X 4 NC Gr.5	1

1500 3 POINT FORK ASSEMBLY




ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	RA-1500	1500 3 Point Fork Weldment	1
2	P728	Cat 1 Draw Pin	2
3	CP-0164-4	Top link Bushing	1
4	064-014-1	Nylock Nut, 3/4"-10 NC	1
5	007-211-1	Hex Head Cap Screw, 3/4-10 X 4 NC Gr.5	1

2000 3 POINT FORK ASSEMBLY



ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	RA-2000	2000 3 Point Fork Weldment	1
2	P728	Cat 1 Draw Pin	2
3	064-014-1	Nylock Nut, 3/4"-10 NC	1
4	007-211-1	Hex Head Cap Screw, 3/4-10 X 4 NC Gr.5	1
5	CP-0164-4	Top link Bushing	1

1500-A 3PT. FORK ASSEMBLY



ITEM	QTY	PART NO	DESCRIPTION
1	1	1500A-FRAME	Frame Weldment
2	1	1500A-30	Fork Pin
3	2	1500A-20	Fork Weldment
4	2	FLA-1209	Set Collar 1 1/4"
5	2	P728	Draw Pin